

# ENSV Inspection Transmittal Summary Report

Media:  
RCRA

Inspection Type:  
CEI

Inspection Date:  
03/24/2105

Preliminary SNC Findings:

Inspector:  
DEDRIEL NEWSOME

Transmittal Date:

NOV / NOPV / NOPF:

Facility Name:  
Midwest Oil Refining Co

Address:  
1900 Walton Road  
St. Louis  
MO  
63114

ID Number:  
MOD006290803

Activity Number: MM Participating Programs:

Federal Activity:  
Petroleum Marketing

Federal Facility:  
No

Potential EJ:  
Yes

SBREFA Provided: Security Handout Provided: MM Screening Completed: EMS ISO 14001: Compliance Officer:  
No EDWIN BUCKNER

Selection Criteria 1:  
Used Oil Processor

Selection Criteria 2:

ACS Code:

## Inspection Findings:

No inspection - facility was closed with no one at site and areas roped off. Appeared abandoned but many tanks observed on-site (photos in memo report). No working phone numbers to contact any company representatives.

## Target Quality:

RCRA



535889



**UNITED STATES ENVIRONMENTAL PROTECTION AGENCY  
REGION 7**

Science and Technology Center  
300 Minnesota Avenue  
Kansas City, Kansas 66101

APR 2 - 2015

**MEMORANDUM**

**SUBJECT:** RCRA Compliance Evaluation Inspection at Midwest Oil Refining Company,  
St. Louis, MO – MOD006290803

**FROM:** Dedriel Newsome, Environmental Engineer *DN*  
ENST/EFCB

**THRU:** *John Houlihan*  
John Houlihan, Chief  
ENST/EFCB

**TO:** Donald Toensing, Chief  
AWMD/ WEMM

At the request of Air & Waste Management Division, I attempted to perform a RCRA compliance evaluation inspection at Midwest Oil Refining Company (Midwest Oil) located at 1900 Walton Road, St. Louis, MO, 63114 on 3/24/2015 (see attachment 1 for aerial photos). However, the facility appeared to be closed as it was roped off, I observed no one on-site, and the solid waste trash dumpster was pad locked (see photos 1 through 4). At 9:15 A.M., I attempted to contact the Site Contact, Julia Lamborn, at 314-401-0397, who is listed in the EPA RCRAInfo database (see attachment 2). I got an answering machine where an apparent male did not identify himself or a company name. Therefore, I left a message identifying myself and cell phone number, letting him know that I was at the facility and trying to reach Ms. Lamborn or someone at Midwest Oil. Also, I attempted to contact the Owner/Operator of the site listed in the database, Glennon Gettinger, at 314-731-3561. The phone number was no longer in service.

Therefore, I contacted the EPA Compliance Officer, Edwin Buckner, and he provided me with the company's phone number from the internet yellow pages, 314-427-2662 and 314-575-8347. The 314-427-2662 phone number is also the number I observed on the company trucks parked on-site. This number could not be completed when called. A recording stated to try again or contact the operator. I contacted the operator and she tried the number and received the same message. The operator stated that when they receive this message, it usually means that the number has changed, is no longer in service, or is a wrong number. When I called the other phone number, 314-575-8347, I got an answering machine and the person identified themselves as "Wayne." I left a message identifying myself and cell phone number, letting them know EPA found this number listed for Midwest Oil, and we were trying to reach someone with Midwest Oil.

Mr. Buckner also gave me a phone number for Midwest Oil Company located in Schiller Park, IL, 847-928-9999. I contacted them and Mr. Iraform stated that they were not related to Midwest Oil Refining Company.





1900 Walton Rd, Overland, MO 63114

My Notes



On the go? Use [m.bing.com](http://m.bing.com) to find maps, directions, businesses, and more



Bird's eye view maps can't be printed, so another map view has been substituted.

ATTACHMENT 1 Page 1 of 2







1900 Walton Rd, Overland, MO 63114

My Notes



On the go? Use [m.bing.com](http://m.bing.com) to find maps, directions, businesses, and more



Bird's eye view maps can't be printed, so another map view has been substituted.

ATTACHMENT 1 Page 2 of 2

## HANDLER INFORMATION REPORT

December 17, 2014

Procedures for Inspectors performing Site Visits

If the facility wants to make a change, they must complete a Notification of Regulated Waste Activity form # MO 780-1164, and send it to the Missouri Department of Natural Resources, Hazardous Waste Program, PO Box 176, Jefferson City, MO 65102-0176. The form can be found at <http://www.dnr.mo.gov/forms/780-1164-f.pdf>

If during the course of the site visit, the inspector/investigator becomes aware of any changes which should be made to the information printed on this form, please make the corrections and return the form to: Beth Koesterer, AWMD/WEMM.

EPA RCRA ID Number: MOD006290803

Name of Company/Site: MIDWEST OIL REFINING CO  
Location of Site: 1900 WALTON RD  
ST LOUIS, MO 63114-5822  
ST LOUIS County

Land Type: Private

NAICS: 324191 - PETROLEUM LUBRICATING OIL AND GREASE MANUFACTURING

Mailing Address: 1900 WALTON RD  
ST LOUIS, MO 63114-5822

Site Contact: JULIA LAMBORN  
Job Title: EXEC DIR  
Address: 1900 WALTON RD  
ST LOUIS, MO 63114-5822  
Email: JULIA0409@AOL.COM  
Phone Number: (314) 401-0397

Current Owner of Site: GLENNON A GETTINGER  
Phone Number: (314) 731-3561  
Owner Type: Private

Current Operator of Site: GLENNON A GETTINGER  
Phone Number: (314) 731-3561  
Operator Type: Private

TYPE(S) OF REGULATED ACTIVITY: Used Oil Transporter  
Used Oil Transfer Facility  
Used Oil Processor  
1st Claimer that Used Oil meets Specification

## Hazardous Wastes Handled:

---

1st N 07/07/80 N 03/22/11 N+

Certified by Notification on 03/22/11 by  
JULIA E LAMBORN 03/18/11  
EXEC DIR

*Not able to complete  
the inspection, therefore  
Not able to verify the  
info.*

Date of Site Visit: 3/24/15

Name of Inspector (Please print): Dedriel Newsome  
(Check one): ☒ EPA R7 ENSV ☐ EPA R7 Contractor ☐ NOWCC/SEE Investigator

Signature of Inspector: Dedriel Newsome



## PHOTO LOG

**Facility Name / City:** Midwest Oil Refining Company  
St. Louis, MO

**Facility ID #:** MOD006290803

**Date :** March 24, 2015

**Photographer:** Dedriel Newsome

**Type of Camera:** Olympus Stylus 720 SW, Serial #: A93671407.

**Digital Recording Media:** Flashcard

**All digital photos were copied by:** Dedriel Newsome on 4/2/15 JEN

**All digital photos were copied to:** CD-R

**Original copy is stored in:** CD-R. Digital photos were downloaded to CD-R all by Dedriel Newsome.

No changes were made in the original image files prior to storage on the CD-R. JEN

Report Photo #	Photographer	Date	Approx. Time*	File Name (DSCNxxxx.jpg)	Description
1	Dedriel Newsome	03/24/15	8:46 AM	1100	Midwest Oil Refining Company, St. Louis, MO (facing SE standing on the NW side of the facility) - The facility appeared to be closed as it was roped off, I observed no one on-site, and the blue solid waste trash dumpster was pad locked. No apparent oil stains were observed in the areas that were visible from the parking lot. It was raining at the time the photo was taken.
2	Dedriel Newsome	03/24/15	8:47 AM	1101	Midwest Oil Refining Company, St. Louis, MO (facing E standing on the NW side of the facility) - The facility appeared to be closed as it was roped off and I observed no one on-site. No apparent oil stains were observed in the areas that were visible from the parking lot. It was raining at the time the photo was taken.
3	Dedriel Newsome	03/24/15	8:47 AM	1102	Midwest Oil Refining Company, St. Louis, MO (facing SE standing on the NW side of the facility) - The facility appeared to be closed as it was roped off and I observed no one on-site. No apparent oil stains were observed in the areas that were visible from the parking lot. It was raining at the time the photo was taken.
4	Dedriel Newsome	03/24/15	8:50 AM	1103	Midwest Oil Refining Company, St. Louis, MO (facing NE standing on the SW side of the facility) - The facility appeared to be closed as it was roped off and I observed no one on-site. No apparent oil stains were observed in the areas that were visible from the parking lot. It was raining at the time the photo was taken.

Midwest Oil Refining Company Photos

St. Louis, MO

3/24/2015

Photos taken by Dedriel Newsome <sup>RFN</sup>

Rope



**PHOTO 1**, 3/24/2015 – Midwest Oil Refining Company, St. Louis, MO (facing SE standing on the NW side of the facility) - The facility appeared to be closed as it was roped off, I observed no one on-site, and the blue solid waste trash dumpster was pad locked. No apparent oil stains were observed in the areas that were visible from the parking lot. It was raining at the time the photo was taken.  
D. Newsome *DN*





**PHOTO 2**, 3/24/2015 – Midwest Oil Refining Company, St. Louis, MO (facing E standing on the NW side of the facility) - The facility appeared to be closed as it was roped off and I observed no one on-site. No apparent oil stains were observed in the areas that were visible from the parking lot. It was raining at the time the photo was taken. D. Newsome

ADN



**PHOTO 3**, 3/24/2015 – Midwest Oil Refining Company, St. Louis, MO (facing SE standing on the NW side of the facility) - The facility appeared to be closed as it was roped off and I observed no one on-site. No apparent oil stains were observed in the areas that were visible from the parking lot. It was raining at the time the photo was taken. D. Newsome



**PHOTO 4, 3/24/2015** – Midwest Oil Refining Company, St. Louis, MO (facing NE standing on the SW side of the facility) - The facility appeared to be closed as it was roped off and I observed no one on-site. No apparent oil stains were observed in the areas that were visible from the parking lot. It was raining at the time the photo was taken. D. Newsome



# DOCUMENT CONTROL SHEET

## DOCUMENT CONTROL CHECK SHEET

Media:

Air	RCRA	Water	Other
X			

Date of Inspection: 3/24/15

Facility/Site Name and Location: Midwest Oil Refining Co.  
St. Louis, MO

IA	KS	MO	NE
		X	

Document		Yes	No	NA
<u>Memo</u> Final Report w/attachments	<u>9</u> Pages	(✓)	( )	( )
Field Sheets	_____ Pages	( )	( )	(✓)
Chain-of-Custody Records <u>for photo CD</u>	<u>1</u> Pages	(✓)	( )	( )
Field Notes	_____ Pages	(✓)	( )	( )
Analytical Data Sheets	_____ Pages	( )	( )	(✓)
Photographic <del>Negatives</del> <u>CD</u>	<u>1</u> <del>Pages</del> <u>CD</u>	(✓)	( )	( )
Photographs (not included w/report)	_____ Pages	( )	( )	(✓)
Pre-inspection Packet	_____ Pages	( )	( )	(✓)
Other Documents (list below)		( )	( )	(✓)
_____	_____ Pages			
_____	_____ Pages			
_____	_____ Pages			

(Note: If additional space is needed to list specific documents, use the reverse side of this page.)

## CERTIFICATION

I, the undersigned, certify that all of the documents pertaining to this activity that were in my possession have been listed above and were included in this package at the time this statement was signed.

*Dedriel Newsome*  
Activity Leader's Signature

4/2/15  
Date Signed

3/24/13

Midwest Oil Refining Co.  
St Louis, MO  
MOB 04 6290543

9:15

314 401 0397 - left message

Not in SVC Glennon # 314 731 3561

Mid Oil Co, Schiller Park IL  
847 928 9999 - not related  
Iraform

314 427-2662 cant be completed

314 575 8347 Wayne - cellphone 29:26 am  
left message

Dodine Newson